



**US Army Corps
of Engineers®**
Walla Walla District

Operations Division

Walla Walla District
Corps of Engineers
201 North Third Avenue
Walla Walla, Washington 99362-1876
February 4, 2015

McNary Lock and Dam Lockage Delay

Locking through the navigation lock at McNary Lock & Dam, located at Columbia River mile 293.0, may require additional time beginning 4 February 2015 until a tainter valve repair is complete.

A fill tainter valve is currently not operational due to the failure of a staff gauge. Until Project personnel can complete the repair, only one fill valve will be available for lockage. This will lengthen vessel lockage time by approximately 15 to 20 minutes (+-).

For additional information, call Operations Division, at (509) 527-7113 or (509) 527-7111.