



**US Army Corps
of Engineers®**

WALLA WALLA DISTRICT

ATTN: CENWW-DE
201 NORTH THIRD STREET
WALLA WALLA WA 99362-1976
HTTP://WWW.NWW.USACE.ARMY.MIL/

DATE: 10/21/2021

POC: Kenny
Koebberling
CENWW-OD B
Walla Walla
District
(509) 527-7364

NOTICE NUMBER: 16906

LOCAL NUMBER: 22-03
WTRWY/CHNL: SNAKE RIVER

LOCK(S): SN 02|SN 03
EFFECTIVE: 10/21/2021 06:30 thru 03/19/2022 23:59
PDT

**LOWER MONUMENTAL AND LITTLE GOOSE
UPSTREAM FLOATING GUIDEWALL RESTRICTIONS**

Until floating guide wall repairs are completed, vessels transiting the Lower Monumental and Little Goose navigation locks must use caution when operating near those project's upstream floating guide walls.

At Lower Monumental, vessels may not tie up to the floating guide wall. Additionally, vessels may not rub against the floating guide wall when approaching or leaving the lock, nor should they use the guide wall as a pivot point for entering the lock. Crew changes for commercial vessels may only take place within the lock chamber when the vessel is properly secured to floating mooring bits.

At Little Goose, vessels may not tie up to the floating guide wall. Additionally, vessels may not rub against the floating guide wall when approaching or leaving the lock, nor may they use the guide wall as a pivot for entering the lock.

PROJECTS AFFECTED:

Lower Monumental Lock and Dam - Snake River Mile 41.6

Little Goose Lock and Dam - Snake River Mile 70.3

These restrictions will remain in place until more substantial repairs can be made to the locks' floating guide wall cables. These repairs are planned for completion by March 2022.

For additional information on this work contact the NWW Operations Division at (509) 527-7364.

//signed//

PAUL A. OCKER
Chief, Operations Division
Walla Walla District, USACE